FIG.1




FIG.2




FIG.3





FIG.4








FIG.5

FIG.6





-1G.7

FIG.8




FIG.9




FIG.10





FIG.11



10/29

FIG.12




FIG.13

46

47

42

FIG.14




FIG.15




FIG.16




FIG.17




FIG.18

7

72

71

73

74

6

413

413

5

M




FIG.20




FIG.21




FIG.22




FIG.23





FIG.24






FIG.25

24; MAGNETRON  $\alpha$ , HIGH-FREGUENCY DRIVE POWER SUPPI 29~7 YAJBA HTT SW5 SO;OVEN **LAMP** 39;FAN MOTOR SW4 SW3 h;נסש**ב**ת ך SW2 SND RELAY 22; DOOR 23; OVEN SWITCH THERMISTOR 3KD яэтаэн яэччү;н FIG.26

20/29

FIG.27




FIG.28




FIG.29





FIG.30






FIG.3

FIG.32




FIG.33




FIG.34




FIG.35




FIG.36




FIG.37




FIG.38

